



**FAA
Airports**

Errata Sheet for Advisory Circular (AC) 150/5200-30C, Airport Winter Safety and Operations

Last Update: 5/31/2013

This errata sheet logs content errors and required updates identified after the Advisory Circular was signed on December 9, 2008. These errors have been corrected in the consolidated PDF version of the AC available on the FAA website.

#	Description of Correction	Location in Document	Rationale	Date Error Corrected
1	Updates Par. 3.3b to recommend the now-finalized SAE ARP 5623, Mobile Digital Infrared Pavement Surface, Ambient Air and Dew Point Temperature Sensor System, for mobile Runway Surface Condition Sensors.	Page 18	SAE G15, Airport Snow and Ice Control Committee, has published SAE ARP 5623, Mobile Digital Infrared Pavement Surface, Ambient Air and Dew Point Temperature Sensor System. This specification had not been finalized when the AC was published in 2008.	3/1/2013
2	Updates Par. 4-6a(1) to add "the latest edition of" before SAE AMS 1435.	Page 30	This change clarifies that airport operators should always use the latest edition of the SAE specification.	5/31/2013
3	Updates Par. 4-6a(2)(i) to add "the latest edition of" before SAE AMS 1431 and to remove the version letter "A" after 1431.	Page 31	This change clarifies that airport operators should always use the latest edition of the SAE specification.	5/31/2013
4	Updates Par. 4-6a(2)(i) to add "the latest editions of"	Page 31	This change clarifies that airport operators should	5/31/2013

	before SAE AMS 1431 and to remove the version letter "A" after 1431.		always use the latest editions of the SAE and MIL specifications.	
--	--	--	---	--